	TM	IC SPEC	CIFICATI	ON	NO. S 12	260
REV:						
COMPILED:	)	CHECKED	)	APPD: //May	SHEET	OF
TITLE:						
11/12/70	jb/					

TEST PROCEDURE

FOR

RTMU-41

			TN	<b>IC</b>	: 5	SP	EC	:IF	A.	TIC	1C				 N	10. 9	s 1	260			
REV:																					
COMPIL	ED:			С	HEC	KEC	):				AP	PD:			s	HEE	Т	1	OF	5	
TITLE:																					

### I. Equipment Required:

- A. VOM, Simpson Model 260, or equivalent.
- B. Oscilloscope, Tektronix (dual trace), or equivalent.
- C. Electronic Counter, Hewlett-Packard 5244, or equivalent.
- D. DDRR-10() Test Set.
- E. Interconnect Test Cables.
- F. Schematic Diagram CK1561.
- G. Timing Chart CH-802

#### II. Preliminary Electrical Tests:

CAUTION: Be sure AC power is removed from RTMU-41

- A. Connect ohmmeter across AC input of unit. Be sure fuses F1 and F2 are in place.
- B. Set AC switch S1 to ON. Continuity should exist across the AC input (approximately 4 ohms). Removing either F1 or F2, or setting S1 to OFF will break continuity.
- C. Continuity should not exist between AC leads and ground. Set S1 to OFF and remove ohmmeter from unit.

# III. Power Supply Voltage Checks:

- A. Insert PC-352/A4549 into A10 and set AC power to ON. Power light DS1 will light. Removing either fuse will cause the power light to go out.
- B. Meter the voltage levels at test points +12V and -12V DC. Voltages should be as indicated +1V DC. Meter the voltage level at test point -27V DC + 2V.
- C. Monitor TP +12V and jumper TP +12 to ground. Remove ground. Voltage level should return to +12V DC. Repeat for test points -12V and -27V DC.
- D. Monitor TP +12 with the high gain scope. The ripple present on TP +12 should be no more than 20 millivolts peak-to-peak. Repeat for test points -12V and -27V DC.
- E. Set AC power switch S1 to OFF. Connect scope probe to DC reset test point. Turn AC power to ON. Level on DC reset test point should rise to approximately +3V DC and then fall and remain at approximately -5 volts.

THE FORM SPEC

			 TN	<b>1C</b>	S	PE	EC	:IF	TC	A.	TIC	<u>10</u>	1			NO.	s	126	50			
REV:																						
COMPIL	ED:			CI	HEC	KED:	:					AP	PD:			SHE	ET	4	0	F	5	
TITLE:																	•					

		READ BAC	K		
BITS	LIGHT 1	2	3	4	5
1,2	ON	ON	OFF	OFF	OFF
2	OFF	ON	OFF	OFF	OFF
1, 3	ON	OFF	ON	OFF	OFF
2 1,2,3	OFF	ON	OFF	OFF	OFF
1,2,3	ON	ON	ON	OFF	OFF
2	OFF	ON	OFF	OFF	OFF
1, 4	ON	OFF	OFF	ON	OFF
2	OFF	ON	OFF	OFF	OFF
1,2, 4	ON	ON	OFF	ON	OFF
2	OFF	ON	OFF	OFF ~	OFF
1, 3,4	ON	OFF	ON	ON	OFF
2	OFF	ON	OFF	OFF	OFF
1,2,3,4	ON	ON	ON	ON	OFF
2,3,4	OFF	ON	ON	ON	OFF
1,2,3,4	ON	ON	ON	ON	OFF
2,3,4	OFF	ON	ON	ON	OFF
1,2,3,4	ON	ON	ON	ON	OFF
2,3,4	OFF	ON	ON	ON	OFF
1,2,3,4	ON	ON	ON	ON	OFF
2	OFF	ON	OFF	OFF	OFF
1, 5	ON	OFF	OFF	OFF	ON
1, 5	OFF	ON	OFF	OFF	OFF
1,2, 5	ON	ON	OFF	OFF	ON
2	OFF	ON	OFF	OFF	OFF
1, 3, 5	ON	OFF	ON	OFF	ON
2	OFF	ON	OFF	OFF	OFF
1,2,3, 5	ON	ON	ON	OFF	ON
2	OFF	ON	OFF	OFF	OFF
1, 4,5	ON	OFF	OFF	ON	ON
2	OFF	ON	OFF	OFF	OFF
1,2,3,4,5	ON	ON	ON	ON	ON
1	ON	OFF	OFF	OFF	OFF
		<u> </u>		1	

C. Set AC power to OFF.D. Record all data on Test Data Sheet.

			ГМ	C SP	EC	IFI	CAT	ON					NO.	s 1	260		
REV:													1	T	ĪĪ		T
COMPILED:				CHECKE	):			APPD	<del></del> :				SHEE	ET	5	OF	<del></del>
TITLE:	·	<del></del>						<u> </u>					<u>.</u>			<del></del>	
								· · · · · · · · · · · · · · · · · · ·									
				· · · · · · · · · · · · · · · · · · ·													
				Test D	at a	She	eet Fo	or RTM	<b>4</b> 11-41	I							
<b>T</b>	D			1 Cb	_1	_											
1.		ver s Vol		ly Che	CKS	•											
	Α,			9+12			VDC	,									
				)-12 <u> </u>		<del></del>	VDC										
		3.		?-27 —			VD(										
		٦,	11	-21	··	<u> </u>	vD(	•									
	В.	Rip	ple	:													
				+12	_		Mi]	livol	ts								
		2.	TP	?-12 <u> </u>			Mil	livol	Lts								
		3.	TP	?-27 <u> </u>			Mi1	livol	ts								
	•	<b>01</b>	. •														
	C.		rti	ng:													
				+12 _			OK										
				2-12 _	······································		OK										
		3.	TP	·-27			OK										
	D.	DC	Res	et TP			ОК		•								
	_																
II.	Inp	ut I	imi	ng Cir	cui	t:											
				/A4494			OK										
•				/A4565			OK							_			
	C.	CTO	ck	Period	Ad	just	ted To	·			_Mi	.11:	isec	ond	S		
III.	Res	et T	'imi	ng And	Ga	ting	Circ	uits:									
,	Α.	PC-	358	/A4566			OK										
	В.	PC-	361	/A4569			OK										
	c.	PC-	359	/A4567			OK										
					<u>-</u>												
IV.	Mem	ory	Shi	ft Reg	ist	er:											
	Α.	PC-	456	/A4710				OK									
Tes	ted	By:			-		<del></del>				Dat	e:					

TMC FORM SPEC 1

24 0 45 ....

REVIS	SION	SHEET		THE TECHNICAL MATE	RIEL CORP. NEW YORK	S 1260 LIST NO.	
DATE	REV.	SHEET	EMN #		DESCRIPTI		APP.
3/24/71	Ø	1		ORIGINAL RELEASE		— · · · · · · · · · · · · · · · · · · ·	
7							
			· · · · · · · · · · · · · · · · · · ·				
					<del> </del>		
					· · · · ·		
				<b>.</b>			
				100 - 100 -			
						·	
		<u> </u>		· · · · · · · · · · · · · · · · · · ·		Arr <del>B</del> aranasa	
		_					
		<del>- </del>				We have a	
					<del>.</del>	The state of the s	
		-					
		-					
							<u> </u>
	<u> </u>		<b> </b>				
ļ	<b> </b>	_	ļ			The state of the s	<b>_</b>
	1	1	1	İ			Ī

			TI	<b>UC</b>		P	EC	:IF	<b>IC</b>	X.	TIC	<b>NC</b>				 N	o. s		1	260	)		
REV:																		·					
COMPIL	ED:			С	HEC	KED	):					API	PD:			SI	HEE	т 2	2	C	) F	5	
TITLE:		 	 																				

F. Power distrubution checks. Measure the following points for voltages and grounds:

CONNECTOR		PIN	
	+12V DC	-12V DC	GROUND
A1	-	4	1,22,A,Z
A2	20	4	1,22,A,Z
A3	20	4	1,22,A,Z
A4	20	4	1,22,A,Z
A5	20	4	1,22,A,Z
A6	20	4	1,22,A,Z
A7	20	4	1,22,A,Z
A8	20	4	1,22,A,Z
A9	20	4	1,22,A,Z

## IV. Input Timing, Reset Timing and Gating Checks:

- A. Set AC power to RTMU to OFF. Inter-connect test set and RTMU. Turn selector switch on test set to RTMU position. Insert PC-316/A4494 into A1 and PC-357/A4565 into A2. Set AC power to ON for the test set and the RTMU. Push Tune Button on Test Set.
- B. Connect frequency counter to TP15 on PC-357/A4565 and adjust R2 for 27.00 msec (100 wpm) or 44.00 msec (60 wpm) ± 0.05 msec. Set AC power to OFF.
- C. Insert PC358/A4566 into A3. Set AC power to ON. Monitor TP2 and push TUNE button on test set and observe a negative pulse. Repeat the above for TP3. Set AC power to OFF.
- D. Insert PC361/A4569 into A6 and set AC power to ON.
  Monitor TP1 and push TUNE button on test set and observe
  positive going pulses. Repeat the above for TP6. Set
  AC power to Off.

			TI	MC	•	P	EC	:IF	-10	A	TI	<u> 10</u>	1				 NO.	. s	126	0			
REV:																			T		T		
COMPIL	ED:		 	c	HEC	KE	):					AP	PD:	<b>4</b>	<b></b>		 SHE	ET	3	OF		 5	
TITLE:											,	<b>-</b>					 						

E. Insert PC-359/A4567 into A4 and set AC power to ON. Push Tune Button On Test Set and observe single negative pulse 13.5 msec (100 wpm) in width on TP16, 21 and 24. Set AC Power to OFF.

## V. Operational Checks:

- A. Memory Shift-Register:
  - 1. Insert PC-456/A4710 into A7 and turn AC power to ON.
- B. Set switches of test set according to following table. Program input to RTMU by pressing (red) tune button. Read back code on lights of test set by using (black) memory advance button. Each time advance (black) button is depressed the bit display will change.

0	Set In
Switch	Position
#'s	1 1
LTR's	A
10 MC	1 1
1 MC	1
100 KC	1
10 KC	$\bar{1}$
1 KC	$\bar{1}$
.1 KC	Ī
RSSA	2
MODE	2
TIME CONSTANT 1	2
TIME CONSTANT 2	2
	<u>~</u>