Teletype Corporation Chicago, Illinois, U.S.A.

725EE Issue 1 February, 1951

## CHANGES AND ADDITIONS TO BULLETINS 1064, ISSUE 2 AND 1080, ISSUE 1 SINGLE MAGNET REPERFORATOR (MODELS 14 AND 20 NONTYPING)

This correction sheet covers parts ordering information for the two newly designed resistor brackets (118440), a new switch bracket (118442), and a new guard (118441) to replace the two 86138 resistor brackets and the 86149 switch bracket. The 86144 switch cover is eliminated.

The three old style parts are no longer manufactured. New style parts can be replaced as a group only.

The following sketch shows the components of the new assembly.

