
+110VDC
-115VAC
UPMID
A
AR
AE
AH
AL
AQ
AM
AN
AP
AT
AU
AV
AW
AX
AY
AZ
AR
AS
T
T
B
LOWLEFT
LOWREMID
LOWRIGHT
UPLEFT
UPMID
UPRIGHT
BC
BD
BE
BF
BG
BH






B
LOWLEFT
LOWREMID
LOWRIGHT
UPLEFT
UPMID
UPRIGHT
REMOVED ALL LINE RELAYS PER LASSA, ITNG


CD
CE


D
E
F
G
H
N
P
R

J
K
L
M