

BREAKOUT

LIST OF MATERIAL

From To Req Item Part No. To Description From

		1	CD101-1-MW	Cord, Nylon, Lacing		
3	6	2	MWC24 (7) U4	Pin 6 (E101)	Pin 1 (T101)	
3	6	3	U5	7	2	
3	6	4	U4	8	4 (T101)	
3	6	5	U5	10	1 (T102)	
3	6	6	U4	11	2	
3	6	7	U5	Pin12 (E101)	4 (T102)	
6	25	8	SJ5	Channel 1	5 (T101)	
6	25	9	SJ4	Channel 2	Pin 5 (T102)	
14	25	10	SJ6	Mike	Standoff	
25	25	11	SJ5	Channel 1	Channel 1	
25	25	12	SJ4	Channel 2	Channel 2	
25	25	13	SJ6	Mike	Mike	
14	20	14	SJ5	Pin 6 (V101)	Term 1 (Mike Plug)	
8	20	15	U7	Pin 7 (V127)	Term 3 (Mike Plug)	
3	8	16	U7	Pin 1 (E101)	Pin 7 (V127)	
10	16	17	U4	Feed Thru	Resistor-10W	
3	17	18	SJ7	Pin 3	C208	
9	19	19	U2	R155 B+	Pin 2 (K101)	
17	19	20	U6	R155(Plate Side)	1 (V112)	
17	19	21	U4	R157	3	
17	19	22	U96	R156(Plate Side)	6	
17	19	23	U94	R158	Pin 8 (V112)	
19	24	24	MWC24 (7) U6	R155(Plate Side)	Meter	
19	24	25	MWC24 (7) U96	R156(Plate Side)	Meter	
19	24	26	MWC24(7)U4	R158	CA2 (Pot)	