					TI	VC	S	P	ΞC	.IF	-10	X.	TIC	NC	1						N	o. s	127	3			
REV:	ø						_																				
COMPILED: L.K.					•	CHECKED: FB							APPD: LA						SHEET				OF				
TITLE:																	<u> </u>										

TEST PROCEDURE FOR TMC FREQUENCY STANDARD

DISTRIBUTION SYSTEM

FOR

SYM1200

	TMC SPECIFICATION													NO.	No. s 1273												
REV:	ø																										
COMPILED: CHECKED:							APPD:							SHE	ET	1	(F	4								
TITLE:																	Ì										

A. TEST EQUIPMENT

- 1. Oscilloscope, Tekronix, 545 or equivalent
- 2. Variac, General Radio W-10MT-3W
- 3. Frequency Standard, TMC house standard
- 4. Frequency Corporator, TMC PFCB-1

B. MECHANICAL INSPECTION

- 1. Inspect the distribution rack to assure:
 - a. All cables are harnessed and routed to preclude pinching, cutting or chafing when a chassis is withdrawn on its slides and tilted for inspection or maintenance.
 - b. Chassis tilting and locking facilities lock the chassis on the servicing position.
 - c. All pointed surfaces are free of scratches or pitting.
 - d. All workmanship conforms to existing TMC standards.

C. ELECTRICAL INSPECTION

- 1. Inspect the distribution rack to assure:
 - a. Proper installation of and application of AC Power Strip.
 - b. Correct termination of all interconnecting cables and plugs.
 - c. Adequate protection of all cables from damage.

D. OPERATIONAL TESTS

- 1. Set the battery switch (S904) on the CSS-2 frequency standards to the "in" position. The Red Battery lights DS902 should go on.
- 2. Set the meter switch (S1001) on the BSPA units to the "condition" position & record the battery condition.
- 3. Set the CSS-2 amplifier switch to the on position.
- 4. Set the CSS-2 meter switch to the voltage position and record on the BSPA the voltage.

TMC SPECIFICATION NO. S 127	
ARRON SHEET O	
COMPILED: CHECKED: APPD: SHEET 2	OF 4
TITLE:	

- 5. Set the meter switch (S1001) to the "discharge" position & record the discharge rate.
- 6. Calculate the DC voltage for steps 4 & 5 above.
- 7. Connect AC power strip. The green power lights (DS901) on the CSS-2 should go on the red power lights will go off.

(NOTE: Allow a sufficient amount of time for the CSS-2 standard to stablize before proceeding)

- 8. Connect the oscilloscope probe to the 100 kHz output jack of standard No. 1 (without releasing the switch) a 100 Kc sinewave of at least 2.8 volt peak to peak should be observed.
- 9. Connect the oscilloscope probe to the 100 kHz output jack of standard No. 1 (without releasing the switch) a 10 Mc sinewave of at least 2.8 volt peak to peak should be observed.
- 10. Connect the oscilloscope probe to the 100 kHz output jack of standard No. 2 (without releasing the switch) a 100 Kc sinewave of at least 2.8 volt peak to peak should be observed.
- 11. Connect the oscilloscope probe to the 100 kHz output jack of standard No. 2 (without releasing the switch) a 10 Mc sinewave of at least 2.8 volt peak to peak should be observed.
- 12. Connect the oscilloscope probe to multicoupler No. 1 output jack No. 1 & observe an open circuit. Release the switch and observe an 1 Mc sinewave output.
- 13. Repeat step 12 for output 2-32.
- 14. Repeat steps (12) and (13) for multicoupler No. 2 outputs jack 9-12, 17-32.
- 15. Connect the oscilloscope probe to multicoupler No. 2 jacks 1 to 8 and 13 to 16 and observe a 1Mc output sinewave.

THE FORM SPEC I

	TMC SPECIFICATION													No. s 1273												
REV:	ø																									
COMPILED: CHECKED:								APPD:								т	3	OF	4							
TITLE:																										

- 16. Connect the metered variac between the power strip and CA-1068-1-12 of CSS-2 No. 1 and record the AC power
- 17. Repeat step 16 for CSS-2 No. 2.

(NOTE: Allow the CSS-2 to warm up for fourteen (14) days before proceeding)

- 18. Connect the 1 Mc output of CSS-2 No. 1 to the test input of the frequency comparator. Connect the 1 Mc output of the house standard to the reference input. Set the PFCB for + 1 part in 109 and record the frequency error for a 24 hours period.
- 19. Repeat step 18 for CSS-2 No. 2.

			TMC	C SPECIFICATION						ON						NO.	S	127	3		
REV:	ø																				
COMPIL				CHECK	ED:					APP	D:					SHEE	T	4	OF	4	
TITLE:																					
																	<u>.</u>				
			<u>T</u>]	EST I	OAT.	A SI	HEE'	<u>r –</u>	C	SS-	2										
В.	Elec	tric	al Iı	nspe	cti	on												_ (ОК		
С.	Mech	anic	al Ir	nspe	cti	on												_ (ОК		
D.	Oper	atio	n																		
	1.	the	h bat unit ht sh	t, tl	ne i	bati	tery	y 1	igl	ht s	shou	1d	be	on,	an	d t	he	pro	rom oper OK		
	2.	(a)	Disc	charg	ge (curi	en†	t											Amps.		
		(b)	Volt	tage														`	Volts		
									1	Dra	in							I	Watts		
	3.		h a.c								the					wer	1 i		t O K		
	4.	(a)	CSS-	-2 No).	1															
			1. 2.	100 10 M				t											OK OK		
		(b)	CSS-	-2 No). :	2															
			1. 2.	100 10 M				t											OK OK		
	5.	(a)	Mult	ico	ıpl	er N	lo.	1													
			Outp	outs	1 1	to 3	32											_ (ОK		
			Mult	ico	ıple	er N	lo.	2													
			Outp	outs	1 1	to 3	32											(ΟK		
	6.	(a)	AC F	Power	. C	SS-2	2 No	ο.	1									v	VATTS		
		(b)	AC F	Power	. C	SS-2	? No	ο.	2									V	VATTS		

REVISION		SHEET	,	THE TECHNICAL MATERIEL CORP. MAMARONECK NEW YORK	S1273 LIST NO.					
DATE	REV.	SHEET	EMN #	DESCRIPTION	· · · · · · · · · · · · · · · · · · ·	APP.				
11/10/70	ø			ORIGINAL RELEASE FOR PRODUCT	· · · · · · · · · · · · · · · · · · ·					
11/10/10				ORIGINAL RELEASE FOR PRODUCT	ION	†				
		1				 				
		-				 				
		<u> </u>								
		1				<u> </u>				
						ļ				
						-				
	-									
		<u> </u>								
			<u> </u>							
	•									
	•									
						1				
					10-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-					
						 				
						 				
		*		<u> </u>						
	· · · ·									
										
										
ļ i			<u> </u>			1				