M.H.S.

JOB 109

APPROVED A. J. J.

_ . .

Equipment:


1-Signal Generator, General Radio Model 1001-A or equivalent 1-V.T.V.M., Hewlitt Packard Model 410-B or equivalent having a low imput capacitance

1-10K ohm, 1-75 ohm carbon resistor, any wattage

TITLE: PRODUCTION TEST-TRANSFORMER, R.F. (TR 019)

Procedure:

Using the following diagram check output at 50KC & 200KC with an input voltage of 1.5V.



Output Voltage --- at 50 KC and 200 KC must be greater than 7.5 v lts.