

DATE 5-3-56  
SH. 1 OF 1  
COMPILED BY

TMC SPECIFICATION NO. S-291


TITLE: INSERTION LOSS TR-001

JOB

APPROVED

*ARB*

Test Set Up



a) Position 1

Set signal generator level V1 for convenient receiver output (V<sub>o</sub>) below overload point and well above noise.

b) Position 2

Without disturbing receiver controls, remove the two TR-001 transformers and connect 6 db pads together. Adjust signal generator output for reference receiver output level (V<sub>o</sub>) indicated as V2.

c) Insertion loss each transformer (since each unit is identical).

$$I.L. = 20 \log \frac{V_2}{V_1}$$